



EXAMPLE REPORT AFTER A VISIT

Visible condition. Clearly recorded.

Example report format. All data in this example are fictional.

CURRENT STATUS



ALL CLEAR

No visible deviations requiring urgent action were observed.

PROPERTY

Apartment - Zadar

VISIT DATE

19 August 2026

PLAN

Plus - visit 2

Visit summary

The visit was completed according to the agreed inspection. Access, visible indoor condition and agreed control points were recorded without observed deviations.

What is sent to the owner

1. Clear status - 2. Photos of relevant points - 3. Note on what was observed

If a problem is observed, OwnerCare documents it and informs the owner through the agreed channel.

Record of visible condition

Access and exterior

Entrance, doors, accessible windows, terrace and post

ALL CLEAR

Indoor space

Visible signs of water, moisture, mould and deviations

ALL CLEAR

Kitchen and bathroom

Agreed check points and visible signs of leaks




ALL CLEAR

Special points

Meters, post or other items by special agreement

BY AGREEMENT

Photographs of relevant points



Note: photographs in the actual report show only agreed and relevant property points.